

**ECR #: P9**

**Tracker #: 13**

**Status: Ratified**

**Title: Correction to Mounting Hole Size in Figure 3.4**

**Release Date: July 25, 1997**

**Impact, High: Possible Impact to Current Motherboard and Rail Designs**

**Spec Version: NLX 1.2**

**Summary:**


The mounting hole size in Figure 3.4 on page 16 of the NLX 1.2 specification is incorrectly called out as a 0.140" hole. It should be specified as a 0.156" hole.

**Background:**

An inconsistency between the mounting holes in Figures 3.2, 3.4, and 3.6 has been noted. The error occurred in Figure 3.4, which calls out the mounting hole as .140" when it should be .156".

**Change Current Specification As Shown:**

Replace Figure 3.4 with the following figure:



**Figure 3.4: NLX Motherboard Dimensions—11.2 inches Primary Side**